



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	GB/CML/QAR19.0001/03	Page 1 of 1
QAR Free Ref. No.:	R14202A/00	Status: Issued
Details of change:	Re-certification Audit	Date of issue: 2021-07-28
Site(s) audited:	CMP Products Ltd Unit 36 Nelson Way Nelson Park East Cramlington Northumberland, NE23 1WH United Kingdom	Valid until: 2024-08-29 Audit date: 2021-07-16
Issuing ExCB:	CML - Eurofins E&E CML Limited	
Manufacturer:	CMP Products Ltd Unit 36 Nelson Way Nelson Park East Cramlington NE23 1WH UK	
Location of Manufacturer:	United Kingdom	
Product information:	Cable glands and accessories	
Protection concept:	CMP Products Ltd Ex d, e, t, nR British Engines (India) Pvt. Ltd Ex d, e, t, Trace Heating	
Related QARs:	<div>GB/CML/QAR19.0001/00</div> <div>GB/CML/QAR19.0001/01</div> <div>GB/CML/QAR19.0001/02</div>	
Related Certificates (manual insertion)::		
Related Certificates (automatic linking)::		
Related Certificates for previous versions:	<div>IECEX CML 18.0171U issue: 1</div> <div>IECEX CML 18.0172 issue: 1</div> <div>IECEX CML 18.0175X issue: 0</div> <div>IECEX CML 18.0177X issue: 1</div> <div>IECEX CML 18.0179X issue: 0</div> <div>IECEX CML 18.0181X issue: 0</div> <div>IECEX CML 18.0183X issue: 0</div> <div>IECEX CML 18.0186U issue: 0</div> <div>IECEX CML 18.0188U issue: 0</div> <div>IECEX CML 18.0190X issue: 1</div> <div>IECEX CML 18.0193X issue: 0</div> <div>IECEX CML 19.0062X issue: 2</div> <div>IECEX SIM 17.0009U issue: 1</div> <div>IECEX CML 18.0171U issue: 2</div> <div>IECEX CML 18.0173X issue: 0</div> <div>IECEX CML 18.0176U issue: 0</div> <div>IECEX CML 18.0178X issue: 0</div> <div>IECEX CML 18.0179X issue: 1</div> <div>IECEX CML 18.0182X issue: 0</div> <div>IECEX CML 18.0184X issue: 0</div> <div>IECEX CML 18.0186U issue: 1</div> <div>IECEX CML 18.0189U issue: 0</div> <div>IECEX CML 18.0191X issue: 0</div> <div>IECEX CML 19.0062X issue: 0</div> <div>IECEX CML 20.0038X issue: 0</div> <div>IECEX SIM 17.0010 issue: 1</div> <div>IECEX CML 18.0172 issue: 0</div> <div>IECEX CML 18.0174 issue: 0</div> <div>IECEX CML 18.0177X issue: 0</div> <div>IECEX CML 18.0178X issue: 1</div> <div>IECEX CML 18.0180X issue: 0</div> <div>IECEX CML 18.0182X issue: 1</div> <div>IECEX CML 18.0185U issue: 0</div> <div>IECEX CML 18.0187U issue: 0</div> <div>IECEX CML 18.0190X issue: 0</div> <div>IECEX CML 18.0192X issue: 0</div> <div>IECEX CML 19.0062X issue: 1</div> <div>IECEX SIM 15.0002X issue: 1</div>	
Comments:		