



ACCESSORIES

C-clamp



For use with un-slotted rungs.

Isolation Pad



Prevent galvanic corrosion between two dissimilar metals.

Contact CMP for more information regarding accessories and substrates.

PPE



CAUTION: We strongly recommend wearing suitable PPE including anti cut gloves.

Please refer to local PPE regulations.

www.cmp-products.com
Tel: +44 (0) 191 265 7411
E-mail: customerservices@cmp-products.com

Cable Cleat Specification

Name	Type	Material	Certification	Size Range	Temp Range	Liner Type	Bolt(s)*
SATURN	QSDSS	Stainless Steel	IEC 61914	13 - 71mm in 19 sizes Quad Formation	-60°C to +60°C	Low Smoke & Fume (LSF) Zero Halogen (LS0H) & Phosphorus Free Polymer	2 x Outer M10 or 1 x Central M10

All products are short-circuit tested. Please visit www.cmp-products.com for further details.

Note: Fixings not included. For more information on fixings please visit www.cmp-products.com and download the Cleat Fixing Pack data sheet. Any other queries please contact CMP via email customerservices@cmp-products.com.


There are no restrictions on the mounting orientation of the cleats.

* The number of bolts used is based on individual site specification.

SATURN CABLE CLEAT

QSDSS


Standard Duty, Stainless Steel, Top Opening, Hingeless, Quad Formation Cable Cleat




FI598 REV03 08/25




CLEAT FITTING INSTRUCTIONS



1. PLACE CLEAT ON MOUNTING SURFACE




2. REMOVE THE NUT AND WASHER




*Booster pad supplied varies based on cleat size


3. REMOVE OR INSERT BOOSTER PAD AS REQUIRED




4. SECURE CLEAT TO MOUNTING SURFACE



5. LAY CABLES IN CLEAT



6. CLOSE CLEAT ARMS



7. TIGHTEN MOUTH BOLT NUT



SECURING CABLES WORLDWIDE